This Page Is Inserted by IFW Operations and is not a part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.


Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
 - GRAY SCALE DOCUMENTS

IMAGES ARE BEST AVAILABLE COPY.


As rescanning documents will not correct images, please do not report the images to the Image Problem Mailbox.

Appl. No. 10/619,922
Amdt. Dated May 14, 2004
Reply to Notice of Missing Parts of
Oct. 15, 2003
Replacement Sheet 2 of 6




SEM image of 0.35 micron via etch with FTM/C $_4\mathbb{F}_6$ /Ar plasma

Appl. No. 10/619,922 Amdt. Dated May 14, 2004 Reply to Notice of Missing Parts of Oct. 15, 2003 Replacement Sheet 3 of 6




SEM image of 0.50 micron via etch with FTM/C $_4$ F $_6$ /Ar plasma

Appl. No. 10/619,922 Amdt. Dated May 14, 2004 Reply to Notice of Missing Parts of Oct. 15, 2003 Replacement Sheet 4 of 6




SEM image of 0.35 micron via etch with $O_2/C_4F_6/Ar$ plasma

Appl. No. 10/619,922
Arndt. Dated May 14, 2004
Reply to Notice of Missing Parts of
Oct. 15, 2003
Replacement Sheet 5 of 6



SEM image of 0.50 micron via etch with $O_2/C_4F_6/Ar$ plasma

Appl. No. 10/619,922 Amdt. Dated May 14, 2004 Reply to Notice of Missing Parts of Oct. 15, 2003 Replacement Sheet 6 of 6



SEM image of 0.30 micron via etch with FTM/C $_4$ F $_6$ /Ar Mixture



Appl. No. 10/619,922 Amdt. Dated May 14, 2004 Reply to Notice of Missing Parts of Oct. 15, 2003 Replacement Sheet 1 of 6




Figure 1




Figure 2